33(1)

From: Investigations Shared Mailbox <Investigations@vline.com.au>

Sent: Friday, 22 November 2024 6:47 PM

To: VLINE-incident-notifications-all; VLINE-incident-notifications-north; VLINE-

incident-notifications-hse; VLINE-incident-notifications-security; VLINE-incident-

notifications-customer; 33(1)

Subject: INC#587635 - Smoke and oil coming from top of car 1357

V/One Incident Logged

Incident number: 587635

The following incident was logged at 18:46 22/11/2024.

Category: Rolling Stock - Engine Fault

Detailed Description:

Around 1353, there was significant smoke coming from the outside of the middle carriage in velocity 57 (TD 8023 to Bendigo) I contacted the driver, who let me know we were going to get to Gisborne station (1 minute away) and she would check it out.

I stepped off the train at Gisborne, and there was lots of smoke and oil pouring out of the top of the train. I myself got covered in ...

oil.

The driver shut off the engines, and proceeded to fault find. I contacted IOC and they arranged buses from Gisborne to

Bendigo.

Coaches arrived at Gisborne approx 1500 all customers on coaches by 1516. (ATTACHMENT - see investigations tab)

Logger: Logged by 33(1) (Employee / Railway Staff)

Reporter: Reported by logger

Impacted: 1 other(s) were impacted.

Time of incident: 14:00 22/11/2024

Location: Type: Main Line

Station/Stop: Gisborne (N)

Brief Summary: Smoke and oil coming from top of car 1357

Drug & alchohol No **test required:**

Attachments: 4 attachment(s) uploaded.

Rail V/Line

Infrastructure Manager:

Operator: V/Line

Train Details: Train Type: VLocity

Traction Type: Diesel

Train Number: 8023

Carriage Number: 1357

Weather Conditions:

Sunny

Inspect full technical details about this incident below.

[* mass Figs.** inclusion**, "inserting reliablests," inserting reliablests." [* mass Figs.** inserting reliablests." inserting reliablests." [* mass Figs.** inserting reliablests." inserting reliablests." [* mass Figs.** inserting reliablests." inserting reliablests. inserting reliable